



| MODEL | A | B | C | D | E | F | G | M | N | Strokes | Weight | Moter |
|---------|-------|-----|-----|------|-----|----|------|------|------|---------|--------|-------|
| 12 Ton | 0-40 | 140 | 190 | 400 | 280 | 30 | 700 | 700 | 1550 | 150 | 400 | 1,5 |
| 20 Ton | 0-50 | 180 | 220 | 500 | 360 | 35 | 800 | 1000 | 1750 | 130 | 600 | 3 |
| 30 Ton | 0-70 | 220 | 290 | 650 | 440 | 40 | 900 | 1100 | 2000 | 120 | 2000 | 4 |
| 40 Ton | 0-70 | 220 | 290 | 650 | 440 | 40 | 950 | 1100 | 2000 | 70 | 2000 | 4 |
| 60 Ton | 0-80 | 240 | 330 | 750 | 480 | 50 | 1000 | 1200 | 2300 | 65 | 3000 | 5,5 |
| 80 Ton | 0-100 | 260 | 370 | 800 | 520 | 50 | 1100 | 1350 | 2500 | 60 | 4000 | 7,5 |
| 100 Ton | 0-100 | 290 | 390 | 850 | 580 | 55 | 1200 | 1500 | 2600 | 60 | 5000 | 10 |
| 120 Ton | 0-120 | 320 | 440 | 900 | 640 | 55 | 1250 | 1700 | 2750 | 55 | 6500 | 12,5 |
| 150 Ton | 0-120 | 350 | 470 | 1000 | 700 | 60 | 1350 | 2000 | 3000 | 50 | 8000 | 15 |
| | mm | mm | mm | mm | mm | mm | mm | mm | mm | /min | Kg | HP |

The dimensions of machine way change according to what the customer needs.